

ATTACHMENT H

Route Map for Hazardous Soil Transportation

The route is as follows:

- Travel northwest on 180th Street to Liberty Avenue
- Turn Left on Liberty Avenue and follow to Interstate 678 North. Note: The truck will pass York College and New York Public School 50.
- Follow Interstate 678 North to Interstate 95 West
- Follow Interstate 95 West over the George Washington Bridge
- Take the Ramp for Interstate 80 West
- Follow Interstate 80 West for approximately 68.5 miles
- Take the ramp for Interstate 180 West
- Follow Interstate 180 West for approximately 99.1 miles
- Take the ramp for US Route 15 North
- Follow US Route 15 North for approximately 90.7 miles
- Follow Interstate 86 west for 37.5 miles
- Turn Left onto Interstate 390 North and follow for 76.2 miles
- Bear left onto Interstate 490 West and follow for 19.3 miles
- Keep Straight on Interstate 90 West for 41.54 miles to Interstate 290 West, bear right
- Follow Interstate 290 West for 9.77 miles and bear Right onto Upper Mountain Road
- Follow Upper Mountain Road for 14.46 miles
- Follow the Robert Moses Parkway Ramp
- Turn right onto Pletcher Road follow to State Route 18 (Creek Road), turn left
- Follow Creek Road to Balmer Road, turn right.




Trip Distance: 487.74 mi

Trip Time: 09:05:10

Start: 180th St

Total Stops: 0

Finish: Balmer Rd



Scale 1 : 2,600,000

1" = 41.04 mi